

Base caps



WMA 162
1 1/16 X 1 1/4



WMA 163
1 1/16 X 1 3/8



WMA 164
1 1/16 X 1 1/8



WMA 165
1 1/16 X 1 1/4



WMA 167
1 1/16 X 1 1/8




WMA 172
5/8 X 3/4


Nosings




WMA 1030
1 1/16 X 1 1/4



WMA 1031
1 1/16 X 1 1/2




WMA 1032
3/4 X 1 1/2



WMA 1033
3/4 X 3 1/2



WMA 1060
1 1/16 X 3 1/2



WMA 1061
1 1/16 X 3 1/2

Base shoes



WMA 120
3/8 X 1 1/16



WMA 121
1/2 X 3/4



WMA 126
1/2 X 3/4



WMA 127
7/16 X 3/4



WMA 129
7/16 X 1 1/16

Quarter rounds



WMA 105
3/4 X 3/4



WMA 106
1 1/16 X 1 1/16



WMA 108
1/2 X 1/2

Rounds



WMA 233
1 1/4



WMA 234
1 1/16